TECHNICAL CHARACTERISTICS



Correct installation:







- Always tighten in the same direction.
- X Never tighten in the opposite direction.







INSTALLATION **TEMPERATURE**



INFLAMMABILITY UI 94 V2



2,5 % ABSORPTION (50 % OF RELATIVE HUMIDITY



Œ

Width mm	Resistance (kg) Norm MIL - S - 23190	Melting point	Oxygen Limit Index (LOL)	Smoke corrosion	Dielectric strength Volts / mm
2,4	8,0	+256 °C	27 %	5 %	50.000
2,5	8,1	+256 °C	27 %	5 %	50.000
2,8	14,0	+256 °C	27 %	5 %	50.000
3,6	18,2	+256 °C	27 %	5 %	50.000
4,8	22,2	+256 °C	27 %	5 %	50.000
7,6	54,4	+256 °C	27 %	5 %	50.000
9,0	79,4	+256 °C	27 %	5 %	50.000
12,6	114,0	+256 °C	27 %	5 %	50.000



- Always store clamps in sealed bags. Once the bag is opened, they must be used as quickly as possible. -
- Never store this product in direct sunlight or near heat sources. -

